

Last Minute Notes for iX Developer 2.52

Build 2.52.48



NOTE

Please note; Below list is not an exhaustive list of issues but covers the most important ones. All data are subject to change without prior notice.

Known issues for iX Developer 2.52

Reference	Known issue
82239	In certain scenarios the Runtime application crashes. The issue is being investigated and a fix is expected later this year (2024).
65073	Password for email device is still stored in clear text. A fix will be implemented in iX Developer 3.0.
70655	The tag events (ResetTag or SetAnalog) do not always work on X2 Base v2.
71552	Setting the MDMEEnabled to true in the registry: HKEY_LOCAL_MACHINE\SYSTEM\CurrentControlSet\Control\Lsa\FipsAlgorithmPolicy will lead to a crash of the application. Note that the setting does not exist on all machines. Workaround is to have it disabled.
48036	Headers and footers do not work when printing reports.
50717	When using full graphic acceleration on Windows 10, sometimes popup-screens can be only partially drawn. Workaround: The problem has to do with accelerated graphics, if you disable window animations, the problem disappears.
56324	If trying to download to panel by manually entering the ip-address, while the network is disabled, iX will crash.

